

## Identification

The square aluminium badge on a 1390131 series keyboard from 1986

All Model M keyboards manufactured by either IBM or Lexmark feature an ID label on the underside indicating the assembly part number, individual serial number, and date the keyboard was manufactured. There are other more obvious ways to distinguish between the range, namely the type of badge featured on the top of the keyboard. The first model Ms (part numbers 1390120 or 1390131) featured a square aluminum IBM badge in the top right corner. Part number 1391401 featured an oval, white IBM logo with grey lettering in the top left of the board. The later IBM manufactured keyboards and subsequent Lexmark keyboards of the early 1990s (IBM assembly part numbers 1370477, 52G9658, 52G9700, 92G7453, 82G2383, 42H1292, and others) featured a similar oval badge to part number 1391401, but instead with a grey background and blue lettering.

## Features by part number

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps	Cable	Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
71U4623 /	Rubber	No	No	PS/2	Yes	blue IBM and	Lexmark	?–1995–?	Lexmark	Removable keys,

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps	Cable	Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
1378706 EC 1387530	Dome					grey label, upper left corner			International, Inc. 1985	Speaker grill & holder w/o speaker, Swedish QWERTY-layout.
1370477	Buckling spring	No	Yes	PS/2	Yes	Blue, left corner	Lexmark	?–1995–?	Lexmark International, Inc. 1984	
1370478	Buckling spring	Yes	Yes	PS/2	Yes	Blue, left corner	Lexmark	1993	Lexmark Int'l. Inc. 1984	M-5, trackball. Left and right click, and L/R "drag" buttons.
1397735	Buckling spring	Yes	Yes	PS/2	No	Oval, left corner, blank	IBM	?–1992–?	IBM Corp. 1984	US 101-key
1386085	Buckling spring	Yes	Yes	AT	No	Grey, left corner	IBM	1988	IBM Corp. 1984	English layout.
1388032	Buckling spring	Yes	Yes	PS/2	No{?}	Silver logo on black metal, right corner	IBM	1985	IBM Corp. 1984	English layout.
1389979	Buckling spring	Yes	Yes	AT	No	Silver, right corner	IBM	1986–87	IBM Corp. 1984	No LED lights for Num/Caps/Scroll lock. Swedish layout.
1390120	Buckling spring	Yes	Yes	AT or PS/2	No	Silver, right corner	IBM	1986–87	IBM Corp. 1984	No LED lights for Num/Caps/Scroll lock
1390131	Buckling	Yes	Yes	AT or	No	Silver, right	IBM	1986–88,	IBM Corp.	

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps Cable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
	spring			PS/2		corner		1993	1984	
1390132	Buckling spring	Yes	Yes	AT or PS/2	No	Silver, right corner	IBM	1986–?	IBM Corp. 1986	French AZERTY layout
1390133	Buckling spring	Yes	Yes	AT or PS/2	No	Silver, right corner	IBM	?–1986–87	IBM Corp. 1984	German QWERTZ layout
1390148	Buckling spring	Yes	Yes	XT	No	Silver, right corner	IBM	?–1986–87	IBM Corp. 1984	No LED lights for Num/Caps/Scroll lock. German QWERTZ layout
1390639	Buckling spring	Yes	No	XT	Yes	Silver, right corner	IBM	?–1987–?	IBM Corp. 1985	Spanish QWERTY layout
1391401	Buckling spring	Yes	Yes	AT or PS/2	No (yes 1992 and after)	Grey (Blue 1992 and after), left corner	IBM	1986–96	IBM Corp. 1984	
1391402	Buckling spring	Yes	Yes	PS/2	Yes ?	Grey (Blue 1992? and after), left corner	IBM UK	1991–96–?	IBM Corp. 1985	French AZERTY layout
1391403	Buckling spring	Yes	Yes (no 1995 and later)	AT or PS/2	Yes	Grey, left corner and also Blue, left corner	IBM UK, Lexmark International	1986–97	IBM Corp./Lexmark International Inc. 1985	German QWERTZ layout
1391404	Buckling	Yes	Yes	AT or	No	Grey, left	IBM UK	1986–?	IBM	Italian QWERTY

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps Cable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
	spring			PS/2		corner			Corporation (no year on label)	layout
1393395	Buckling spring	Yes	Yes	PS/2	No	Grey, left corner	IBM UK	1985–?	IBM Corporation 1985	Italian QWERTY layout
1391405	Buckling spring	Yes	Yes	AT or PS/2	No	Black/Blue, left corner	IBM	1986–?	IBM Corp. 1985	Spanish QWERTY layout
1391406	Buckling spring	Yes	Yes	AT or PS/2	No	Grey, left corner	IBM	≤1985–99	IBM United Kingdom	UK 102-key variant
1391407	Buckling spring	Yes	Yes	PS/2	Yes	Grey, left corner	IBM	?–1994–96–?	IBM United Kingdom	Danish/Icelandic 102-key
1391409	Buckling spring	Yes	Yes	PS/2	No	Gray, left corner	IBM	1987?–94?	IBM Corp. 1985/Lexmark Int. 1985	Norwegian 102-key
1391410	Buckling spring	Yes	Yes	PS/2 (or AT?)	No	Gray, left corner	IBM UK	?–1992–?	IBM Corp. 1985	Portuguese 102-key
1391411	Buckling spring	Yes	Yes	AT or PS/2	No	Gray/blue, left corner	IBM UK	?–1987–97–?	IBM Corp. 1985	Swedish 102-key
1391414	Buckling spring	Yes	Yes	PS/2	No	Gray, left corner	IBM UK	?–1996–?	IBM Corp. 1985	Belgian AZERTY layout
1391412	Buckling spring	Yes	Yes	PS/2	No	Gray, left corner	IBM UK	1987–96	IBM Corp.	Swiss French/German QWERTZ layout, 102-key

<a href="#">[hide]</a> Part Number	Key Type	Detachable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
		Keycaps	Cable							
1391472	Buckling spring	Yes	Yes	AT or PS/2	No	Gray, left corner	IBM	1987–91	IBM Corp. 1984	Space saver; no numeric keypad or lights
1391506	Buckling spring	Yes	Yes	PS/2	No	Gray/blue, left corner and also grey left corner	IBM de Mexico	1990	IBM Corp. 1984	Spanish QWERTY layout
1391511	Buckling spring	Yes	Yes	PS/2	No	Blue, left corner	IBM UK	1990–93	IBM Corp. 1985	Dutch 102-key
1392565	Buckling spring	Yes	No	8P5C (RJ-45)	Yes	Grey, left corner	Lexmark (for IBM)	?–1995	Lexmark International, Inc. 1984	Keyboard for terminals such as IBM 3151. Line drawing characters on the numeric keypad. "Page Up"/"Page Down" replaced with "Clear"/"Erase EOF". Bottom row consists of "Ctrl", "Reset", spacebar, "Ctrl", "Send". Speaker grill on bottom of unit.
1392934	Buckling spring	Yes	Yes	AT or PS/2	No	Gray, left corner	IBM	?–1987–90–?	IBM Corp. 1984	Space saver; no numeric keypad or lights

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps Cable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
1393464	Buckling spring	Yes	Yes	PS/2	No{?}	Grey, left corner	IBM	?-1989-92-?	IBM Corp. 1984	Same as 1391401, with special key-caps: Used for airline reservations
1393669	Buckling spring	Yes (no after ????)	Yes (no after 1994)	AT or PS/2	partial after 1995, yes after ????	Gray label, left corner / Blue label, left corner / IBM sign, below LEDs	Lexmark UK, IBM UK / Unicomp	198?-200?	Lexmark International Inc. 1985 / IBM Corp. 1985 / Unicomp 1996	Slovenian / Croatian (former YU) QWERTZ layout; with or without speaker grill on bottom of unit
1394064	Buckling spring	Yes	Yes	PS/2	No	?	Lexmark	?-1996-?	Lexmark International, Inc. 1984	
1394540	Buckling spring	Yes	Yes	PS/2	No	Gray, left corner	IBM	1990-91?	IBM Corp. 1984	Made for IBM RS/6000 computer. Contains real speaker.
1398601	Buckling Spring	Yes	Yes	AT 5-din or Ps/2	Yes	Lexmark logo, left corner	Lexmark	?-1993-?	Lexmark Int'l Inc 1984	
1394542	Buckling spring	Yes	Yes	PS/2	Yes	Gray/blue, left corner	IBM UK	1991-94?	IBM Corp. 1985	German QWERTZ layout
1394545	Buckling spring	Yes	Yes	PS/2	No	Gray/Blue, left corner	IBM UK, Lexmark	1990-96?	IBM Corp. 1985 / Lexmark International Inc. 1985	Made for IBM RS/6000 computer. Contains real speaker.

<a href="#">[hide]</a> Part Number	Key Type	Detachable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
		Keycaps	Cable							
										Swedish/Finnish 102-key QWERTY layout.
1394958	Buckling spring	Yes	Yes	PS/2	Yes	Silver on black, left corner	IBM UK	?–1998–?	IBM Corp. 1985	German QWERTZ, dark gray industrial version
1394966	Buckling spring	Yes	Yes	PS/2	?	Silver on black, left corner	IBM UK	1992	IBM Corp. 1985	Swedish 102-key, dark gray industrial version
1395300	Buckling spring	No	No	PS/2	No	Blue, top right right	IBM	1990–93	IBM Corp. 1984	Model M2; Shipped with IBM PS/1
1396790	Buckling spring	Yes	Yes	PS/2	Yes (no 1991)	Grey (Blue 1992 and after), left corner	IBM	?–1991–95?	IBM Corp. 1985	Made in UK by IBM; North American layout
1397003	Buckling spring	Yes	Yes	PS/2	?	Blue, top left	IBM	?–1993–99?	IBM Corp. 1985	Made in UK by IBM; German QWERTZ; 122 Keys
1397000	Buckling spring	Yes	Yes	PS/2	?	Blue, top left	Lexmark (for IBM)	?	Lexmark International, Inc. 1984	122-key terminal emulation keyboard: Home/Rule key with arrow keys in a "plus" layout, 24 function keys, 10-

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps Cable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
										key left cluster with terminal commands (Attn, Clear, Pause, ErEOF, etc.)
1397599	Buckling spring	Yes	Yes	PS/2	Yes	Gray, left corner	IBM	?–1993–?	IBM Corp. 1984	
1397681	Buckling spring	No	Yes	PS/2 (or AT?)	Yes	Gray, left corner (later Blue)	IBM	?–1991–93–?	IBM Corp. 1984	Space saver; no numeric keypad or lights
1399625	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Lexmark, IBM UK	?–1994–?	Lexmark International Inc. 1985	Terminal keyboard; speaker grill on bottom of unit; no lights
13H6705	Buckling spring	No	No	PS/2	Yes	Silver, left corner	Lexmark, Maxi Switch	1994–98	Lexmark International, Inc. 1984, or None (on Maxi Switch models)	Trackpoint, two connectors for keyboard and mouse, the only Model M to come in Black
42H1292, 92G7453, 92G7483	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Lexmark, IBM UK	1993–99	Lexmark International, Inc. 1984	
42H1292U	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Unicomp	1996–	Unicomp, Inc. 1984	Optional AT/DIN adapter
51G8572	Buckling	Yes	Yes	PS/2	Yes	Gray/Blue, left	IBM,	1993–96	IBM Corp.	Model M; shipped



<a href="#">[hide]</a> Part Number	Key Type	Detachable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
		Keycaps	Cable							
	spring					corner	Lexmark, IBM UK		1984, Lexmark International, Inc. 1984	with IBM RS/6000; speaker on bottom of unit
52G9658	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Lexmark	?–1993–?	Lexmark International, Inc. 1984	Model M; speaker grill on bottom of unit
52G9700	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Lexmark	1993–99	Lexmark International, Inc. 1984	Model M; speaker grill on bottom of unit
70G8638	Rubber Dome	No	No	PS/2	Yes	Square, top right	Lexmark	?–1994–?	Lexmark International, Inc. 1984	Speaker grill on bottom of unit, silkscreen keycaps
71G4621	Dome switches	Yes	No	PS/2	Yes	Blue, left corner	Lexmark (for IBM)	?–1996–?	Lexmark International, Inc. 1984	Danish QWERTY layout
71G4622	Dome switches	No	No	PS/2	Yes	Blue, left corner	Lexmark (for IBM)	?–1995–?	Lexmark International, Inc. 1984	Dutch QWERTY layout, 1378705, EC1391461
71G4625	Dome switches	No	No	PS/2	Yes	Grey, left corner	Lexmark (for IBM)	?–1993–96–?	Lexmark International, Inc. 1985	German QWERTZ layout
71G4630	Dome switches	No	No	PS/2	Yes	Blue, left corner	Lexmark (for IBM)	?–1994–?	Lexmark International, Inc. 1984	Italian QWERTY layout
71G4643	Dome	Yes	No	PS/2	Yes	Blue, left	Lexmark	?–1995–?	Lexmark	

<a href="#">[hide]</a> Part Number	Key Type	Detachable Keycaps Cable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
	switches					corner			International, Inc. 1985	
71G4644	Dome switches	No	No	PS/2	Yes	Blue, left corner	Lexmark	?–1993–95–?	Lexmark International, Inc. 1984	
8131276	Buckling spring	No	No	RJ25	Yes	Blue, Upper-right corner	IBM UK	?–1997	IBM Corp.	
82G2383	Buckling spring	Yes	No	PS/2	Yes	Blue, left corner	Lexmark	1993–99	Lexmark International, Inc. 1984	
82G3281	Buckling spring	No	No	PS/2	Yes	?	Lexmark	1994–95	Lexmark International, Inc. 1984	White trackpoint, two connectors for keyboard and mouse
82G3295	Buckling spring	Yes	No	PS/2	Yes	Blue "IBM", top left corner	Lexmark	?–1995–?	Lexmark International, Inc. 1984	
06H4173	Buckling spring	No	No	PS/2	Yes	?	Unicomp	1998–99	Unicomp, Inc. 1984	Industrial PS/2 trackpoint, two connectors for keyboard and mouse
UB40R46	Buckling spring	No	No	PS/2	Yes	?	Unicomp	?–	Unicomp, Inc. 1984	104 key, customizable layout.

<a href="#">[hide]</a> Part Number	Key Type	Detachable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
		Keycaps	Cable							
UB4044A	Buckling spring	No	No	USB	Yes	None	Unicomp	?–	Unicomp, Inc. 1984	104 key, customizable layout (USB version).
02K3817	Buckling spring	Yes	No	PS/2	Yes	None	Unicomp	?–	Unicomp, Inc. 1984	German layout unicomp keyboard
UNI0T56	Buckling spring	No	No	PS/2	Yes	None	Unicomp	?–2003–?	?	122 key, laid out for use with PC/5250 emulators; produces standard 101-key scancodes with keys that are not present on a standard keyboard mapped to standard keys with modifiers (e.g., F24 appears to the PC as shift+F12)
1386887	Buckling spring	Yes	No	Terminal DIN-5	No	Square metal, black on silver. Upper right.	IBM	?–1986–?	IBM Corp. 1985	122 key 3179 terminal keyboard
1389194	Buckling spring	Yes	No	Terminal DIN-5	No	Square metal, black on silver. Upper right.	IBM	?–1986–?	IBM Corp. 1984	122 key 3179/3192 terminal keyboard, APL keycaps
1369182	Buckling spring	No	No	PS/2	Yes	"DELL" logo, grey on white,	Lexmark "Made in the	?–1993–?	Lexmark International,	Latin American QWERTY Layout

<a href="#">[hide]</a> Part Number	Key Type	Detachable		Interf.	Drainage Channels	Label Type, Position	Maker	Years	Copyright	Miscellaneous Features
Part Number	Key Type	Key Caps	Cable	Interface	Drainage Channels	Label Type/Position	Manufacturer	Dates of Manufacture	Copyright	Misc features
1369050	Buckling spring	No	No	PS/2	Yes	upper left corner "DELL" logo, grey on white, upper left corner	USA" Lexmark "Made in the USA"	?-1995-?	Inc. 1984 Lexmark International, Inc. 1984	US Standard QWERTY Layout

Note: The manufacture dates are approximate. Click "Show" to display the uncollapsed table.